










Sunny Swift

GOOD VIBRATIONS



CS-STAN ALLOWS A STANDARD CHANGE WHERE A TACTILE/KINAESTHETIC STALL WARNING INDICATOR SYSTEM IS LINKED TO EXISTING STALL WARNING SYSTEMS. WE EXPECT THIS KIND OF NEW EQUIPMENT WILL SOON BECOME AVAILABLE ON THE MARKET.

You can find links to:

- CS-STAN Issue 4, point CS-SC252a 'INSTALLATION OF A TACTILE STALL WARNING INDICATOR SYSTEM', and
 - stall warning systems
- in the 'Related Content' section.

Please, send your comments and ideas to:
generalaviation@easa.europa.eu

Join the GA Community!
www.easa.europa.eu/community/ga